

Greetings from the Villages in Partnership Malawi Office.

I am writing to provide an update on the water project, which is nearing completion. In our August progress report, we outlined the remaining works as follows:

- Conduct water quality testing (physico-chemical and bacteriological) in accordance with Malawi Bureau of Standards standards prior to full community handover.
- Train Water Point Committees for the five borehole wells.
- Erect project visibility signage at all drilled boreholes.
- Formal handover of the boreholes to the community.

I am pleased to share that the water quality testing has been completed, and the report is attached.

The Water Point Committees training was conducted last week, and the report is currently being prepared by the responsible officers.

Visibility signage has been erected at all five boreholes. I have attached a photograph of one of the constructed signposts. To complete the wording on the posts, I have also shared the proposed signage design for Rotary's review and approval so that VIP may proceed with finalizing the signage.

Once the signage is complete, we will coordinate with the Rotary Club of Blantyre to formally hand over the boreholes to the targeted communities.

I look forward to hearing your thoughts on the signage design.

Kind regards,

Phillip

Water Point Committees

Nsenda Water Point Committee



Mwala Water Point Committee



Manduwasa Water Point Committee



Maliwata Water Point Committee



Makuluni Water Point Committee



Water Sample Collection at Nsenda Borehole



A Constructed Sign Post at Makuluni

